
NOT SUPPORTED										
AIRFIELD NAME			September 25		FIFE			EGPJ	Scotland	
CALLSIGN					FIFE Traffic			122.800 Unio	com	
LOCATION		Lat	Lat N056.11.00.000			Long W003.13.13.000			Elev. 396ft QFE= QNH-13 HPs	
LOCATION		2.3nm SW of G			Glenrothes cross roads/roundabout				Unlicensed Airfield	
CHART SOURCE		Fife	Airport	SPECI	AL RULES	During Parac	During Parachuting, ALL A/C must call for START_UP			
METAR AIR	PORT	RT EGPH 1131.35 "canopies active/in the air" = A/F closed, no start-ups, no inbounds, no taxiing.							nds, no taxiing.	
NAV AIDS	None	ne; See chart below for								
RUNWAY	Head	lings	-		Surface	Whilst persons on A/F, start-ups, no taxiing, no landings.				
	06/2				Asphalt	ALL A/C MUST adhere to Noise Abatement rules, see charts.			les, see charts.	
AIRSPACE	CLAS		Transition level 3000ft			Airspace above is Class C Scottish FIR, FL195				
CIRCUITS	1000	'QFE	All Circuits	South	outh; SEE CHART 06 RT hand; 24 LFT hand. OHJs @2000'QFE (A2400) preferred.					
NO FLY	G	lenrot	thes town; I	Kinglass	sie Village;	Portmoak A/F.				
LOCAL		Portmoak A/F 3.6nm N by W; Intense Gliding. High ground, up to 1512ft AMSL to the NW of A/F.								
HAZARDS		Numerous single and multiple Wind Turbines, up to 350'AGL causing severe turbulence downwind.								
HELICOPTE	RI	Approaches / departures as per Fixed Wing. Routing to helipad/Hanger hard standings (if doors								
OPERATION	us C	closed), from Final if permitted. Hover taxi to/from Fuel point North, ONLY when approved by ATC								
CDECIAL		(traffic). Rotors stopped before fuelling. Call for restart and lift. (traffic)								
SPECIAL										
RULES		ALWAYS FLY the NOISE ABATEMENT CIRCUIT as below Also see separate document 'Circuits at EGPJ' Pilots should call Fife radio not less than 5nm inbound, pass callsign, position and request A/F								
REMARKS		information. Use (and report) VRPs below if possible. NOTE NON-STANDARD CIRCUIT.								
INLIVIANNO		RW EGPJ has NO A/F lighting - DAYLIGHT operations only.								
NOISE		NOTE NON-STANDARD CIRCUIT. DO NOT OVERFLY KINGLASSIE or THE HOUSING ESTATE PENALTY								
ABATMENT		Have another try. NO OHJs. Dead side join, centre runway @A2000ft 115M. descend after runway.								
		Strictly at Pilot's own risk. ONE only at anytime. A Mobile mooring mast is available in the field to the								
AIRSHIP	5	South of Taxi Echo and the road. IF A/F OPEN, ALL Approaches / departures from/to the South, no								
OPERATIO	NS ti	turns and max 800'QFE, (A1400') North of railway line. DO NOT OVERFLY A/F IF ACTIVE.								
	Т	The fuel point for ALL A/C. is on the Northern apron, next to Hold B.								
CIX CLUB		TAXIING: FOXTROT EXERCISE CAUTION BEFORE ENTRY. There could be traffic in either direction.								
OPERATIO		NOTE, the designated CIX Club taxiways and parking spurs are well drained mesh reinforced grass.								
		Pilots venture onto other grass surfaces at their own risk.								
PENALTY FOR OVERFLYING KINGLASSIE or HOUSING ESTATE 24- GO AROUND; 09- DO A T&										
	1	0300	- Ala						VORs	
ALL!	7		C c	35		1	1 1		PTH 110.400MHz R167/347 16nm	
Kennoway								K107/347 10IIIII		
								SAB 112.500MHz		
PC	IDING	MAOK Glenrotes R314/134 38r							R314/134 38nm	
		χ,			B Methil					
	NTRE								GOW 115.4MHz	
Tal and		Buckhaven							R071/251 45nm	
Ballingry										
The state of the s	P. V								108.90	
- Like	1000 m	- Address - Wiscardendeni							(max 30nm of	
(Kelty	2	NS12 O EGPH								
-975		763								
Wealdy Forum								Use NAV2!		
EGPH CTR Cowdenbeath CKCaldy EGPH CTA										

VRPs A. Bonneybank. A/F: N056.13.04.000 W003.01.13.370 PlanG/Little Nav Map 56.2177777 -3.0203805 PlanG/Little Nav Map 56.2007833 -3.1307611

B. Markinch Rlwy Stn N056.12.02.820 W003.07.50.740

C. Thlomands (Lake) N056.13.56.910 W003.15.16.610 PlanG/Little Nav Map 56.232475 -3.2546138

N056.11.48.380 W002.56.03.770 PlanG/Little Nav Map 56.1967722 D. Largo Bay -2.9343805 Portmoak A/F AVOID N056.11.28.270 W003.19.52.850 PlanG/Little Nav Map 56.1911861 -3.3313472



ABOVE: General view of A/F layout.

BELOW: CIX APRONS and Parking Details






The chart on the left shows the circuit overlaid on the FSX scenery. THIS CIRCUIT IS VERY TIGHT. You must not overfly Kinglassie or the housing estate, which means R24 landing has a VERY short approach ON THE RUNWAY HEADING. Essentially, your base leg is just the turn from the farm. It requires careful planning and speed and height control.

R06 departures, you need to turn onto 110° as soon as you can and identify your turning points, to avoid leaving the circuit.


There is a more comprehensive explanation of the Circuits on on page 4 with pictures.

THIS IS A VERY TIGHT, NON-STANDARD CIRCUIT. YOU WILL NEED TO PRACTICE IT BEFORE FLYING WITH OTHER A/C ALL PILOTS: PLEASE PUT YOUR A/C CALLSIGN AFTER YOUR NAME. NOT TO BE USED FOR RW OPERATIONS

The Circuit charts below, modified and reproduced by kind permission of the A/F management(RW).



RUNWAY 06 CIRCUIT; RIGHT-HAND CIRCUITS: Departing Runway 06, right turn to a heading of app. 110° to avoid the housing estate ASAP. Base Leg is West of the village of Kinglassie. DO NOT OVERSHOOT the turn to final - very little space/time for correction.




RUNWAY 24 CIRCUIT; LEFT-HAND CIRCUITS: departing Runway 24, extend upwind leg beyond Kinglassie. Turn crosswind, pass West of Kinglassie. NOTE offset final for Runway 24, avoiding the housing estate.

On Base, report final when approximately 50° from the runway, and overfly the Golf Course.



24 Circuit: Outbound leg, Turn before or at edge of Quarry.
You can drift north but **NOT SOUTH**




Cross the road to the south of the Quarry, Heading 150° turn at the right edge of the scrubland (an outcrop).




Now on a Heading 060° remain South of the line. Note the farm beyond the wood. Check speed, slow to descend.



Check U/C down. 10^o flap MAXIMUM Turn around white factory, over small roundabout just left of yellow factory



DO NOT overfly 2nd roundabout. Look for the police centre and call final. NO MORE FLAP, control SPEED




WATCH YOUR HEIGHT. CALL FINAL. Look for the Police Station complex and grounds. Aim just left of complex



YOU WILL NOT SEE THE RUNWAY so look for the Golf Clubhouse, turn before it. Check speed and height.



This is the scary bit. I am too high. DO NOT LOOK FOR RUNWAY NOT VISABLE yet.




Look for the 3 clumps, the leftmost is on the c/l. If too high, runway in sight. FULL FLAP judge the turn.



If you turned a bit early, look for the ditch, follow it in. This is a bit low. WATCH YOUR SPEED. If you need to Go-Around, power up and climb, high ground right and ahead. Propjets use reverse thrust. If needed over the fence.



060° Departure. Passing 500ft (earlier if safe). Head 110° to pass between the Police complex and another yellowish factory. Your turn MUST be as soon as safe. REMAIN CLEAR OF THE POLICE COMPLEX.



As soon as possible, identify yellow and bluish factory, exit via roadway. Turn onto 065M by abeam the farm. Final turn; Start before railway/road, avoid Kinglagssie and you will be just north of the C/L. Late and you will be too far north to recover the C/L.